



## Safety Message of the Day for IMEA Members



### **Slow Hands On Hot Work**

Energized work punishes rushing. Most contacts happen during transitions—changing grips, passing tools, or repositioning. Slow down, think through each move, and communicate before acting. If something doesn't feel right, stop the job and speak up. A short pause now prevents a life-changing incident later.

***Crew check: What's the highest-risk move in today's job?***

***Our goal is simple - no surprises, no shortcuts, and everyone goes home  
If conditions change, we stop and reset the plan***